



Landesgesellschaft  
Österreich

## Zertifikat der Leistungsbeständigkeit Zertifikat- Nr.: 0033 – CPR – 2011

Gemäß der Verordnung (EU) Nr. 305/2011 des Europäischen Parlaments und des Rates vom 9. März 2011 (Bauproduktenverordnung - CPR), gilt dieses Zertifikat für das Bauprodukt

### Super-Rail

Aufhaltestufe:	N2	H2/L2	H4b/L4b
Normalisierter Wirkungsbereich:	W2	W4	W7
Anprallheftigkeitsstufe:	A	A	A
Normalisierte dyn. Durchbiegung:	0,5m	0,8m	2,0m
Normalisierte Fahrzeugeindringung:	NPD	VI4	VI7
Beständigkeit Schneeräumung:		Klasse 3	

Dauerhaftigkeit: verzinkt nach EN ISO 1461 oder alternativ nach EN 10346

In Verkehr gebracht durch  
**UNIPROMET d.o.o.**  
**Bulevar oslobodilaca 92a**  
**32103 Konjevici, Cacak**  
**Serbia**

und in folgendem Werk gefertigt  
**UNIPROMET d.o.o.**  
**Bulevar oslobodilaca 92a**  
**32103 Konjevici, Cacak**  
**Serbia**

Dieses Zertifikat bescheinigt, dass alle Vorschriften über die Bewertung und Überprüfung der Leistungsbeständigkeit im Anhang ZA.1.b der harmonisierten Norm

**EN 1317-5:2007+A2:2012/AC:2012**

entsprechend System 1 angewendet werden und dass das Bauprodukt alle darin vorgeschriebenen Anforderungen erfüllt.

Dieses Zertifikat wurde erstmals am 28.03.2011 ausgestellt auf Basis des Bewertungsberichts 26780\_UNI\_rev1/06.08.2019 und bleibt gültig, solange sich die in der harmonisierten Norm genannten Prüfverfahren oder Anforderungen der werkseigenen Produktionskontrolle zur Bewertung der Leistung der erklärten Merkmale nicht ändern und das Produkt und die Herstellbedingungen im Werk nicht wesentlich geändert werden.

Wien, 06.08.2019



(Dipl.-Ing. Gerald Bachler)

TÜV SÜD Landesgesellschaft Österreich GmbH Zertifizierungsstelle für Produkte Arsenal, Objekt 207 1030 Wien

Landesgesellschaft  
Österreich

## Anhang zum Zertifikat der Leistungsbeständigkeit Zertifikat- Nr.: 0033 – CPR – 2011

**Für das Bauprodukt****Super-Rail****In Verkehr gebracht durch****UNIPROMET d.o.o.****Bulevar oslobodilaca 92a  
32103 Konjevici, Cacak****Modifikation 1:**Genehmigt am  
12.04.2011Korrosionsschutz von Schutzplankenholmen:

Der Korrosionsschutz von Schutzplankenholmen Profil A (L1.1-101) und Profil B (L1.1-102) erfolgt als Stückverzinkung nach EN ISO 1461 (Ausgabe 10/2009) oder alternativ durch die Verwendung von kontinuierlich schmelztauchveredeltem Stahlband („Bandverzinken“) mit Zink (Z)- nach EN 10346-S250GD+Z600 bzw. mit Zink-Aluminium (ZA)-Überzug nach EN 10346-S250GD+ZA300 (Ausgabe 10/2015).

Gegenständliche Modifikation wurde im Prüfbericht 15915 beurteilt und bewertet.

**Modifikation 2:**Genehmigt am  
16.04.2012Meterlochung:

Für die Schutzplankenholme Profil A (L1.1-101) und Profil B (L1.1-102) ist eine Verwendung von Holmen mit Zusatzlochung bei 1,0 m und 3,0 m („Meterlochung“) gleichwertig möglich. Gegenständliche Modifikation wurde im Prüfbericht 19250 beurteilt und bewertet.

**Modifikation 3:**Genehmigt am  
27.12.2012Schutzplankenholme A- und B-Profil:

Verwendung von Schutzplankenholmen Profil A (L1.1-101) und Schutzplankenholmen Profil B (L1.1-102) in Verbindung mit den jeweils zugehörigen Bauteilen ist gleichwertig möglich. Gegenständliche Modifikation wurde im Prüfbericht 16975\_Rev1 beurteilt und bewertet.

**Modifikation 4:**Genehmigt am  
16.02.2015Änderung Verschraubung zwischen Holm und Deformationselement:

Die HRK-Schraube mit Nase M 16x45, 4.6 mit Mutter 5 (40.01) soll durch die HRK-Schraube mit Sechskant M 16x45, 8.8 mit Mutter 8 (40.04) ersetzt werden. Gegenständliche Modifikation wurde im Bericht 28268\_1 beurteilt und bewertet.

**Modifikation 5:**Genehmigt am  
23.12.2016Wegfall Schrauben bei geändertem Stoßverbinder:

Bei Verwendung des geänderten längeren Stoßverbinders können bei der Kastenprofil-Stoßverbindung die beiden M 14 Schrauben weggelassen werden. Gegenständliche Modifikation wurde im Bericht 28268\_3\_Rev02 beurteilt und bewertet.

**Modifikation 6:**Genehmigt am  
23.12.2016Änderung Verschraubung zwischen Kastenprofil und Pfosten:

Die Modifikation beschreibt den Ersatz der Schraube mit Sechskant M 10x45, 4.6 mit Mutter 5; ISO 4034 (RAL-Teil Nr. 40.42) durch Schraube mit Sechskant M 10x45, 8.8 mit Mutter 8; ISO 4032 (RAL-Teil Nr. 40.54) beim Anschluss zwischen Kastenprofil und Pfosten. Gegenständliche Modifikation wurde im Bericht 28268\_5 beurteilt und bewertet.

Wien, 06.08.2019



(Dipl.-Ing. Gerald Bachler)



Landesgesellschaft  
Österreich

## Certificate of constancy of performance Certificate - No.: 0033 – CPR – 2011

In compliance with Regulation 305/2011/EU of the European Parliament and of the Council of 9 March 2011 (the Construction Products Regulation or CPR), this certificate applies to the construction product

### Super-Rail

Containment level:	N2	H2/L2	H4b/L4b
Normalized working width:	W2	W4	W7
Impact severity:	A	A	A
Normalized dynamic deflection:	0.5m	0.8m	2.0m
Normalized vehicle intrusion:	NPD	VI4	VI7
Resistance to snow removal:		Class 3	

durability: galvanized according to EN ISO 1461 or alternatively to EN 10346

placed on the market by  
**UNIPROMET d.o.o.**  
**Bulevar oslobodilaca 92a**  
**32103 Konjevici, Cacak**  
**Serbia**

and produced in the manufacturing plant  
**UNIPROMET d.o.o.**  
**Bulevar oslobodilaca 92a**  
**32103 Konjevici, Cacak**  
**Serbia**

This certificate attests that all provisions concerning the assessment and verification of constancy of performance described in Annex ZA 1.b of the standard

**EN 1317-5:2007+A2:2012/AC:2012**

under system 1 for the performances set out above are applied and that the construction product fulfils all the prescribed requirements for these performances.

This certificate was first issued on 28.03.2011, based on the assessment report 26780\_UNI\_rev1/06.08.2019 and will remain valid as long as the test methods and/or factory production control requirements included in the harmonised standard, used to assess the performances of the declared essential characteristics, do not change, and the construction product, and the manufacturing conditions in the plant are not modified significantly, unless suspended or withdrawn by the product certification body.

Wien, 06.08.2019



TÜV SÜD Landesgesellschaft Österreich GmbH Zertifizierungsstelle für Produkte Arsenal, Objekt 207 1030 Wien

Landesgesellschaft  
Österreich

**Annex to**  
**certificate of constancy of performance**  
**Certificate - No.: 0033 – CPR – 2011**

**For the construction product Super-Rail**

**Placed on the market by UNIPROMET d.o.o.**  
**Bulevar oslobođenica 92a**  
**32103 Konjevici, Cacak**

**Modification 1:**

Approved on  
12.04.2011

Corrosion protection of beams:

Corrosion protection of the A-beam (L1.1-101) and B-beam (L1.1-102) can be done via hot dip galvanizing according to DIN EN ISO 1461:2009 or alternatively via continuous galvanizing according to DIN EN 10346:2009 with steel bands with zinc(Z) (DIN EN 10346-S250GD+Z600-N-A-C) or respectively with zinc-aluminum(ZA) (DIN EN 10346-S250GD+ZA300 and ZA600-N-A-C)-coating. The mentioned modification was judged and assessed in the test report 15915.

**Modification 2:**

Approved on  
16.04.2012

Meter holes:

The rails profile A and profile B may be modified with additional elongated holes according to RAL-Drawing no. L1.1-101 and L1.1-102. The mentioned modification was judged and assessed in the test report 19250.

**Modification 3:**

Approved on  
27.12.2012

Equivalence of A and B profile:

The A-beam (L1.1-101) and B-beam (L1.1-102) with the additionally needed parts can be seen as equivalent. The mentioned modification was judged and assessed in the test report 16975\_Rev01.

**Modification 4:**

Approved on  
16.02.2018

Change of nut and bolt between beam and deformation element:

The round head bolt with nose M 16x45, 4.6 with nut 5 (40.01) should be replaced by the round head bolt with hexagon M 16x45, 8.8 with nut 8 (40.04). The mentioned modification was judged and assessed in the report 28268\_1.

**Modification 5:**

Approved on  
23.12.2016

Omission of bolts with adapted butt joint:

When using the adapted longer butt joint, the two M 14 bolts can be omitted in the box profile butt joint. The mentioned modification was judged and assessed in the report 28268\_3\_Rev02.

**Modification 6:**

Approved on  
23.12.2016

Change of nut and bolt between box profile and post:

The modification describes the replacement of the bolt with hexagon M10x45, 4.6 with nut 5; ISO 4034 (RAL part No 40.42) with a bolt with hexagon M10x45, 8.8 with nut 8; ISO 4032 (RAL Part No. 40.54) connecting the box profile and the post. The mentioned modification was judged and assessed in the report 28268\_5.

Wien, 06.08.2019



TÜV SÜD Landesgesellschaft Österreich GmbH Zertifizierungsstelle für Produkte Arsenal, Objekt 207 1030 Wien